

PRÀCTICA N° 4 maig 2003

%540

N05 G55
N06 G58 Z63.5
N10 T6 D6
N15 G96 S80
N20 M03
N25 G00 X35 Z3 F0.1
N30 R20=540 R21=23 R22=0 R24=0.1 R25=0.1 R26=0.5 R27=42 R28=0.1 R29=31
R30=0.5 L95 P1
N35 R20=540 R21=23 R22=0 R24=0 R25=0 R26=0 R27=42 R28=0.05 R29=21 R30=0.5
L95 P1
N40 G00 X35 Z15
N42 G04 X5
N45 T2 D2
N50 G00 X24 Z-4.5
N55 G01 X21 Z-4.5
N56 G00 X26 Z-4.5
N60 G00 X26 Z-8.5
N65 G01 X21 Z-8.5
N66 G00 X26 Z-8.5
N70 G00 X35 Z15
N75 M30

L540

N05 G01 X23 Z0
N10 G01 X23 Z-12.5
N15 G01 X14 Z-23.5 B2
N20 G01 X20 Z-33.5
N25 G01 X25
N30 M17

%541

N05 G55
N7 G58 Z63.5
N15 T6 D6
N20 G96 S80
N25 M03
N30 G00 X35 Z15 F0.1
N35 R20=541 R21=10 R22=0 R24=0.1 R25=0.1 R26=0.5 R27=42 R28=0.1 R29=31
R30=0.5 L95 P1
N40 R20=541 R21=10 R22=0 R24=0 R25=0 R26=0 R27=42 R28=0.05 R29=21 R30=0.5
L95 P1
N45 G00 X35 Z15
N50 M30

L541

N05 G01 X10 Z0
N10 G01 X10 Z-4
N15 G01 X16 Z-12 B2
N20 G01 X10 Z-20 B-1.5
N25 G01 X20 Z-30 B-1.5
N35 G01 X18 Z-35
N40 G01 X25
N45 M17